

Incident:

June 19, 2010 6DF2 Heater Fire Investigation

EPA Region 10
Deemed Releasable

Date:

19-Jun-10

Recommendations / Corrective Actions from the Investigation Report (see Tab name for investigation

Manage the dry point of the stream, monitor the corrosion rates within the convection coil.

No information was found regarding activity or closure of these action items. However, this process unit, CRU1, was shutdown on April 17, 2013 and has not operated since that time. Therefore, these action items are no longer applicable.

Prevent liquid water from leaving 6D-E4 and entering 6D-F2

1. through increased sampling and monitoring.
Three annual internal inspections on the coil verified the dry
2. point management is working.
Phase 2 investigation of sources of NH₄Cl salts discontinued due to sufficient information from other studies and corrective
3. actions.
4. Learning session with HTU/CRU#1 Operations conducted in May 2011.

Due Date:

N/A

Assigned to:

N/A

reference):